Oil Field Environmental Incident Summary

Incident: 20150802155307 Date/Time of Notice: 08/02/2015 15:53

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: CACTUS 149-92-35B-05H TF

Field Name: HEART BUTTE Well File #: 29788

Date Incident: 8/1/2015 Time Incident: 16:00 Facility ID Number:

County: DUNN Twp: 149 Rng: 92 Sec: 35 Qtr: NW NE

Location Description: Incident limited to well site.

Submitted By: Tony Lucero Received By:

Contact Person: Chuck Antle

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

There was no release. The incident involved a water tank fire.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Fire hazard. Personnel were isolated a safe distance from the fire.

Areal Extent:

There was no spill. The fire was confined to the well site.

Potential Environmental Impacts:

There were no environmental impacts.

Action Taken or Planned:

Investigating ignition source. Will implement appropriate protective measures based on investigation results.

Wastes Disposal Location: No waste was generated.

Agencies Involved: BIA, BLM, Three Affiliated Tribes

Updates

Date: 8/3/2015 Status: Reviewed - Assigned to Other Agency Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release occurred on tribal lands. BIA/Tribe retains oversight.